



JON M. HUNTSMAN, JR.
Governor
GARY R. HERBERT
Lieutenant Governor

State of Utah
DEPARTMENT OF NATURAL RESOURCES
Division of Oil, Gas & Mining

MICHAEL R. STYLER JOHN R. BAZA
Executive Director Division Director

Inspection Report
Minerals Regulatory Program
September 23, 2005

Supervisor 1027

Mine Name: Brown's Canyon Rock Quarry
Operator Name: Rock Products of Utah, Inc.

Permit number: M/043/017
Inspection Date: Sept. 22, 2005
Time: 9:00 am to 10:25 am

Inspector(s): Lynn Kunzler and Dan Smith, DOGM
Other Participants: Tony Mecham
Mine Status: Active

Elements of Inspection	Weather: clear		
	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Concurrent Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads,	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Soils	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
9. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Purpose of Inspection:

This was a routine inspection while in the area. Last inspection was in May of 2004.

Inspection Summary:

- During the May 2004 inspection, it was discovered that the operation had expanded beyond the permitted area. The Operator was issued a notice of non-compliance (pre-enforcement rules) and was required to submit an amendment to his mining and reclamation plan. This amendment was approved in December of 2004. The reclamation surety update was requested by January 31, 2005. To date, we have not received the updated reclamation surety. During this inspection, it was noted that there had been significant increase in the disturbed area to the south and west. Using the GPS, we surveyed the current disturbed area to compare with what had previously been permitted. The current disturbed area extends significantly beyond the current permit area (approximately 4.11 acres).
- The operator was reminded to salvage soil materials prior to expanding the waste dump to the north.
Photos and GPS data in mine file.

Conclusions and Recommendations:

- Cessation Order #MC-05-01-14(1) was issued for expanding operations beyond the permit area. Abatement requires the operator to submit an amendment to his mine plan and to increase the surety to cover (at a minimum) the current disturbed area.

Inspector's Signature

Date: September 23, 2005

LK:jb

O:\M043-Summit\M0430017-BrownsCynRock-RockProducts\inspections\insp-09222005.doc